

**Workshop on
THE BASICS OF DECOMMISSIONING OF RESEARCH REACTORS
Manila, Philippines
16-20 October 2006**

AGENDA

Monday 16 October 2006	Tuesday 17 October 2006	Wednesday 18 October 2006	Thursday 19 October 2006	Friday 20 October 2006
09.00 – 09.15 Welcoming Address	08.00 – 09.30 Management of Decommissioning Projects (L. Boing)	08.00 – 09.30 Decontamination Technologies (L. Boing)	08.00 – 09.30 Dismantling Technologies (L. Boing)	08.30 – 10.30 Practical Exercise Presentations (P. McIntyre)
09.15 – 10.15 Regulatory Requirements (E. Warnecke, IAEA)	09.30 – 10.30 Safety Related Documentation (D. Draper)	09.30 – 10.30 Health and Safety Concerns (E. Warnecke)	<i>09.30 – 10.00 Break</i>	<i>10.30 – 11.00 Break</i>
<i>10.15 – 10.45 Break</i>	<i>10.30 – 11.00 Break</i>	<i>10.30 – 11.00 Break</i>	10.00 – 12.00 Waste and Spent Fuel Management (D. Draper)	11.00 – 12.30 General Discussions and Conclusions (E. Warnecke)
10.45 – 11.45 Decommissioning Process (L. Boing, USA)	11.00 – 12.00 The Transition Phase (L. Boing)	11.00 – 13.00 Member State Presentations (4)	<i>12.00 – 13.00 Lunch</i>	12.30 – 13.00 Closing Address
11.45 – 12.45 Decommissioning Planning (D. Draper, USA)	12.00 – 13.00 Cost Estimate and Financial Mechanisms (P. McIntyre, IAEA)	<i>13.00 – 14.00 Lunch</i>	13.00 – 14.00 Release from Regulatory Control (E. Warnecke)	
<i>12.45 – 13.30 Lunch</i>	<i>13.00 – 14.00 Lunch</i>	14.00 – 15.00 Recordkeeping (D. Draper)	14.00 – 15.30 Member State Presentations (3)	
13.30 Start of tour to reactor facility	14.00 – 15.30 Radiological Monitoring during Decommissioning (D. Draper)	15.00 – 16.00 Member State Presentations (2)	<i>15.30 – 16.00 Break</i>	
	<i>15.30 – 16.00 Break</i>	<i>16.00 – 16.30 Break</i>	16.00 – 17.30 Practical Exercise III (P. McIntyre)	
	16.00 – 17.30 Practical Exercise I (P. McIntyre)	16.30 – 18.00 Practical Exercise II (P. McIntyre)		